




2008 COOK INLET ECOREGION LAKES SURVEY PHOTOS



Photos courtesy of the Alaska Department of Environmental Conservation

Lakes were accessed via floatplane or roads. DEC Photos.



The Habitat Crew conducted habitat surveys at ten sites around each lake, documenting habitat types , collecting macro invertebrate and diatom specimens. UAA Environment and Natural Resource Institute partnered with DEC to complete biological analysis. DEC photos.





The Index Site Crew obtained lake profiles, water chemistry, plankton, and sediment samples at the deepest part of each lake. DEC photos.

Downloading
lake profiles
from CTD.



Obtaining
water
chemistry
samples with
Integrated
Sampler.



Washing down
plankton in
Plankton Net
Collection Cup.



Sediment
sample
obtained with
Sediment
Corer.





Fish tissue samples were collected for analysis by DEC's Environmental Health Fish Monitoring Program (<http://www.dec.state.ak.us/eh/vet/fish.htm>). DEC Photos.

