

PATH: V:\Project Drawings\Gaffney FILE: 091-GAF-GWA-F3.DWG PLOTTED: 1/9/07.



EXPLANATION	
MW8	MONITORING WELL LOCATION (LETTER S DESIGNATES A SHALLOW WELL, LETTER D FOR DEEP)
378/6.50	TRICHLOROETHENE RESULTS (ug/L)
	TETRACHLOROETHENE RESULTS (ug/L)
ND	NOT DETECTED

SOURCE: AERIAL PHOTO RCHRDSN_HWY7-20-06_16-3_1'PIX.JPG
 DATED 7/20/06 PROVIDED BY AERO-METRIC ANCHORAGE.



oasis
 ENVIRONMENTAL
 825 W. 8TH AVENUE, SUITE 200
 ANCHORAGE, ALASKA 99501

DATE: JAN. 2007
 CHKD: B.J.M.
 DRAWN: NO
 PROJ. NO: 14-091

**GROUNDWATER ANALYTICAL
 RESULTS FOR PCE AND TCE**

GAFFNEY ROAD GROUNDWATER ASSESSMENT
 Fairbanks, Alaska